


FUGITIVE OR SMOKE EMISSION INSPECTION
EPA METHOD 22 for OUTDOOR LOCATION

Company <u>Waste Management</u> Site <u>Cottonwood Hills</u> Company Rep <u>Mike McElvain</u>	Observer <u>Mike McElvain</u> Affiliation <u>WM</u> Date <u>9.29.16</u>
---	---

Sky Conditions <u>P.C.</u> Precipitation <u>No</u>	Wind Direction <u>NNE</u> Wind Speed <u>0-5 mph</u>
---	--

Process Unit* <u>Open Flame</u> Current Monitoring Frequency <u>Quarterly</u> *(Flare, Solidification, Crusher, Diesel Engine)	Operational Status <u>ON</u>
--	------------------------------

Sketch process unit. Indicate observer position relative to the source. Indicate potential emission points and/or actual emission points.



OBSERVATIONS

	Clock Time	Observation period duration (min:sec)	Accumulated emission time (min:sec)	
Begin Observation	<u>0945</u>			
	<u>1000</u>	<u>10 min</u>	<u>Ø</u>	
	<u>1015</u>	<u>10 min</u>	<u>Ø</u>	
	<u>1030</u>	<u>10 min</u>	<u>Ø</u>	
	<u>1045</u>	<u>10 min</u>	<u>Ø</u>	
	<u>1100</u>	<u>10 min</u>	<u>Ø</u>	
		<u>10 min</u>	<u>Ø</u>	
End Observation	<u>1100</u>	<u>60 minutes</u>	<u>Ø</u>	Totals

Not applicable if checked:

Date & time visible emissions noted:

Date & time corrective action initiated:

Name:

Description of corrective action:

WM02693